


CORNER RESTORATION

CORNER C 1/4 29 TWP 13 S RANGE 33 E

ORIGINAL SURVEY BY:

CONTRACT NUMBER:

CONTRACT DATE:



ORIGINAL DESCRIPTION:

This corner has not been previously established.

RESTORATION BY, STAMP AND DATE:

OREGON EAST ENGINEERING, INC.
P.O. BOX 277
MT. VERNON, OREGON

NOVEMBER, 1977

RECEIVED AND FILED

NOV 25 1977

John Liveira
JOHN LIVEIRA, County Clerk

By _____ Deputy

REGISTERED
PROFESSIONAL
LAND SURVEYOR
Douglas M. Ferguson
OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

EVIDENCE FOUND:

N/A


DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

Set a 2 1/2" x 30" galvanized iron pipe and brass cap marked as shown in the ground. Raised a small mound of stones up around the pipe. No bearing trees were available.

Compass variation 20° E.

MONUMENT MARKED



Complete and File with Office of the Grant
County Surveyor, Grant County, Oregon,
Courthouse, Canyon City, Oregon 97820