


CORNER RESTORATION

CORNER S 1/4 29 TWP 13 S RANGE 33 E

ORIGINAL SURVEY BY: JOHN B. DAVID

CONTRACT NUMBER: 131

CONTRACT DATE: JUNE 8, 1869



ORIGINAL DESCRIPTION:

Set stone 16 x 9 x 7 for 1/4 Section Corner.

RESTORATION BY, STAMP AND DATE:

OREGON EAST ENGINEERING, INC
P.O. BOX 277
MT. VERNON, OREGON

NOVEMBER, 1977

RECEIVED AND FILED

NOV 25 1977

John Liveira
JOHN LIVEIRA, County Clerk

By _____ Deputy

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Douglas M. Ferguson
OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

EVIDENCE FOUND:

No evidence was found. Set corner by single proportion.


DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

Set a 2 1/2" x 30" galvanized iron pipe and brass cap marked as shown in the ground. Raised a small mound of stones up around the pipe. No bearing trees were available.

Compass Variation 20° E.

MONUMENT MARKED



Complete and File with Office of the Grant
County Surveyor, Grant County, Oregon,
Courthouse, Canyon City, Oregon 97820