


CORNER RESTORATION

CORNER SE cor 29 TWP 13 S RANGE 33E

ORIGINAL SURVEY BY: JOHN B. DAVID

CONTRACT NUMBER: 131

CONTRACT DATE: JUNE 8, 1869



ORIGINAL DESCRIPTION:

Set stone 16 x 9 x 6 for corner to Sections 28, 29, 32, and 33.

RESTORATION BY, STAMP AND DATE:

OREGON EAST ENGINEERING,
P. O. BOX 277
MT. VERNON, OREGON

RECEIVED AND FILED

NOV 25 1977

JOHN LIVEIRA, County Clerk

By _____ Deputy

REGISTERED
PROFESSIONAL
LAND SURVEYOR

DOUGLAS M. FERGUSON
848

NOVEMBER, 1977

EVIDENCE FOUND:

Found original 16 x 9 x 6 stone lying loose on a slope. Found remains of a mound of stone close by the corner stone. Position was accepted due to its harmony with other found corners.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:


Show how trees are scribed and basis of bearings, including compass var.

Set a 2 1/2" x 30" galvanized iron pipe and brass cap marked as shown in the ground. Raised a mound of stones up around the pipe from which:

A Juniper, 10" in diam., bears N22°W a distance of 37.5 ft. scribed T13S R33E S29 BT. Attached a bearing tree sign to the BT.

Compass variation 20°E.

MONUMENT MARKED



Complete and File with Office of the Grant
County Surveyor, Grant County, Oregon,
Courthouse, Canyon City, Oregon 97820