


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

T.13S., R.34E., INDEX C-3

History of original corner establishment:

This corner was not previously established.



Description of corner evidence found:

This corner was not previously established.

Description of monument and accessories I establish to perpetuate the original location of this corner:

At the position determined by survey, Land Partition Plat 2007-_____, Set a 2-1/2" x 30" aluminum pipe monument w/3" dia. cap stamped as shown in the DIAGRAM, 18" in the ground, raised a 1' high x 3' dia. mound of earth and stone, from which:

A 5/8" iron pin w/yellow plastic cap bears N80°51'W, 10.10 ft.

A 5/8" iron pin w/yellow plastic cap bears N21°47'E, 10.73 ft.

A 10" dia. Juniper bears N78°34'E, 64.95 ft., scribed C1/4 S6 BT.

A 5/8" iron pin w/yellow plastic cap bears S08°39'E, 11.09 ft. set in a mound of stone.

DIAGRAM

T13S R34E
C 1/4

S6
2007
PLS 49865

Yellow plastic caps on 5/8" pins are marked "FSE"

Measurements to accessories taken with Topcon Hyper-Lite GPS.

I hereby certify that the above corner point was perpetuated as shown hereon on November 13, 2007

Witness: D. Mitchell Ferguson, LSIT
David H. Herburger, Surv. Tech.

Office of County Surveyor County of Grant

State of Oregon. I hereby certify that the within instrument was filed in this office for record on the 17 day of JAN, ~~2007~~ **2008**

Robert D. Baggett by _____
County Surveyor Deputy

See Grant County Land Partition Plat 2007- 28



RENEWAL DATE:
01/01/2008