


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

T.13S., R.34E., INDEX C-5

History of original corner establishment:

This corner was originally established by John B. David under G.L.O. contract No. 131, dated June 8, 1869. Survey General notes state:

Set stone 17x9x6 for 1/4 sec. corner.



Description of corner evidence found:

No evidence of this corner is found. Set monument at proportionate measure.

Description of monument and accessories I establish to perpetuate the original location of this corner:

At proportionate position determined by survey, Land Partition Plat 2007-_____, Set a 2-1/2" x 30" aluminum pipe monument w/3" dia. cap stamped as shown in the DIAGRAM, 14" in the ground, raised a 2' high x 3' dia. mound of earth and stone, from which:

- A 5/8" iron pin w/yellow plastic cap bears N49°09'W, 15.02 ft.
- A 5/8" iron pin w/yellow plastic cap bears N32°23'E, 12.74 ft.
- A 5/8" iron pin w/yellow plastic cap bears S36°31'E, 18.36 ft.
- A 5/8" iron pin w/yellow plastic cap bears S50°02'W, 14.37 ft.

Yellow plastic caps on 5/8" pins are marked "FSE"

Measurements to accessories taken with Topcon Hyper-Lite GPS.

I hereby certify that the above corner point was perpetuated as shown hereon on November 13, 2007

Witness: D. Mitchell Ferguson, LSIT
David H. Herburger, Surv. Tech.

Office of County Surveyor _____ County of Grant
State of Oregon. I hereby certify that the within instrument was filed in this office for record on the 5th day of NOVEMBER, 2007-2010

[Signature] by _____
County Surveyor Deputy

See Grant County Land Partition Plat 2007- 28

DIAGRAM

T13S R34E
1/4
S6 | S5
2007
PLS 49865



RENEWAL DATE:
01/01/2008