


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

T.13S., R.34E., INDEX E-4

History of original corner establishment:

This corner was not previously established.



Description of corner evidence found:

This corner was not previously established.

Description of monument and accessories I establish to perpetuate the original location of this corner:

At the position determined by survey, Land Partition Plat 2007-_____, Set a 2-1/2" x 30" aluminum pipe monument w/3" dia. cap stamped as shown in the DIAGRAM, 12" in the ground, raised a 1' high x 3' dia. mound of earth and stone, from which:

A 5/8" iron pin w/yellow plastic cap bears N08°57'W, 7.76 ft.

A 5/8" iron pin w/yellow plastic cap bears S01°40'E, 9.85 ft.

DIAGRAM

T13S R34E

S6

E 1/16-----

S7

2007

PLS 49865

Yellow plastic caps on 5/8" pins are marked "FSE"

Measurements to accessories taken with Topcon Hyper-Lite GPS.

I hereby certify that the above corner point was perpetuated as shown hereon on November 13, 2007

Witness: D. Mitchell Ferguson, LSIT
David H. Herburger, Surv. Tech.



RENEWAL DATE:
01/01/2008

Office of County Surveyor _____ County of Grant
State of Oregon _____. I hereby certify that the within instrument was filed in this office
for record on the 5th day of NOVEMBER, 2007 2010

[Signature] by _____
County Surveyor Deputy

See Grant County Land Partition Plat 2007- 28