


CORNER RESTORATION

N $\frac{1}{4}$ corner
CORNER Sec. 8 TWP 13 S RANGE 34 E

ORIGINAL SURVEY BY: John B. David

CONTRACT NUMBER: 131

CONTRACT DATE: June 8, 1869



ORIGINAL DESCRIPTION:


West on a true line between Secs. 5 and 8.

40.00 set stone 18x7x6 for $\frac{1}{4}$ section corner in ravine bearing N.E.


RECEIVED AND
FILED

RESTORATION BY, STAMP AND DATE:

R. D. Baggett
A. R. Crapo



Robert D. Baggett



June 11, 1981

JUL 11 1981

OFFICE OF COUNTY SURVEYOR

Robert D. Baggett

Attest: *Jennie Lawrence*

Grant County Surveyor

EVIDENCE FOUND:

Found basalt stone 18x7x6 inches lying on its side marked $\frac{1}{4}$. This stone had tipped over to the North and was lying with the marks clearly preserved as the marked side was down. This stone was in a dim ring of stone and remains of a mound.

I accept the position of this stone for the $\frac{1}{4}$ corner, it is harmoniously related to other known corners in the area.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At the corner point:

MONUMENT MARKED

Set a 1 $\frac{1}{2}$ "x30" galvanized iron pipe 22 inches in the ground with brass cap marked as shown.

I buried the original corner stone, inverted, West and alongside the iron pipe and surrounded the pipe with a mound of stone, 3 ft. diam. to top of cap.

No bearing trees or suitable bearing objects available.

This corner is 100 feet East of a fence corner of fences running South and West.

