


CORNER RESTORATION

CORNER: NW1/16 SEC. 7, TWP. 13 S., RANGE 34 E.,

ORIGINAL SURVEY BY: Corner Not

CONTRACT NUMBER: Previously Established

CONTRACT DATE:



ORIGINAL DESCRIPTION: None

RESTORATION BY, STAMP AND DATE:

M.C. Springer
R.D. Bagett

RECEIVED AND
FILED

Sept 29, 2003
OFFICE OF COUNTY SURVEYOR
R.D. Bagett
ATTEST: *Michael C. Springer*

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Michael C. Springer

OREGON
JULY 9, 2002
MICHAEL C. SPRINGER
#70918

EXPIRES: 6/30/2004

SEPTEMBER 22, 2003

EVIDENCE FOUND: None

See Record Map of Survey No. 1676


DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

At the corner point: I set a 2½"x30" aluminum pipe,
18" in the ground, with attached Bagett-Griffith and Blackman
aluminum cap marked as shown.

REFERENCE POINTS:

A 5/8"x30" iron pin, bears S72°31'E, 174.9 ft., with
attached yellow plastic cap marked
BGA SURVEYOR MARKER

A 5/8"x30" iron pin, bears N21°38'W, 148.4 ft., with
attached yellow plastic cap marked
BGA SURVEYOR MARKER



Raised a mound of stone 4 ft. base to top of cap. Used RTK-GPS to measure
to the RP's which are on the southerly right of way of County Road No. 61,
As set in Record Survey No. 866.