

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. N-4

History of original corner establishment:

None. Corner established this survey.

DIAGRAM

T13S R35E
S18
E1/16—
S19
1992
PLS 2405

Description of Corner Evidence Found:

None. Corner established this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the DIAGRAM, 27" in the ground.

From Which:

Douglas Fir, 16" dia., bears N40°15'W, 8.5 ft., scribed: E1/16 S18 BT
White Fir, 12" dia., bears S58°30'E, 30.7 ft., scribed: E1/16 S19 BT

Measurements to BT's taken with a magnetic compass, declination 20° East, and a nylon clad steel tape. Set steel fence post with Land Survey Monument (54-9) and Property Boundary (54-2) signs 5' south and west of the monument. Nailed a brass washer stamped PLS 2405 on blaze above BT scribe as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument (54-9) signs on back of each tree as required. Painted a 6" red band above Bearing Trees signs and painted blaze red.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 26, 1989
SUSAN E. NEWSTETTER
2405

Exp: 12/31/94

This work was performed by:
Susan E. Newstetter PLS 2405
Witnessed by: D. Mitchell Ferguson
and Rick Saul
October 5, 1992
Refer to Grant Co. Survey No.: 1236

Office of Sumner County of Grant
State of OR I hereby certify that the within instrument was
filed in this office for record on the 20 day of June, 19 93
Robert D. Boren by _____
(COUNTY OFFICIAL) (DEPUTY)

N-4