

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. P-3

History of original corner establishment:

None. Corner established this survey.

DIAGRAM
T13S R35E
C1/4
•
S 19
1992
PLS 2405

Description of Corner Evidence Found:

None. Corner established this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the DIAGRAM, 26" in the ground.

From Which:

Ponderosa Pine, 12" dia., bears N06°27'W, 30.7 ft., scribed: C1/4 S19 BT
Ponderosa Pine, 16" dia., bears N69°09'E, 24.0 ft., scribed: C1/4 S19 BT
Ponderosa Pine, 10" dia., bears S44°01'E, 12.6 ft., scribed: C1/4 S19 BT
Douglas Fir, 12" dia., bears S62°43'W, 31.3 ft., scribed: C1/4 S19 BT

Measurements to BT's taken with an Electronic Tacheometer with bearings based on the survey control network. Set steel fence post with Land Survey Monument (54-9) sign 5' north of the monument. Nailed a brass washer stamped PLS 2405 on blaze above BT scribe as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument (54-9) signs on back of each tree as required. Painted a 6" red band above Bearing Trees signs and painted blaze red.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 26, 1989
SUSAN E. NEWSTETTER
2405

Exp: 12/31/94

This work was performed by:
Susan E. Newstetter PLS 2405
Witnessed by: D. Mitchell Ferguson
and Rick Saul
October 5, 1992
Refer to Grant Co. Survey No.: 1236

Office of Surveyor County of Grant
State of Or I hereby certify that the within instrument was
filed in this office for record on the 20 day of Jan, 1993
Robert D. Brown by
(COUNTY OFFICIAL) (DEPUTY)