

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. R-3

History of original corner establishment:

Corner was originally established by Bamford Robb, in March 1881, under General Land Office Contract No. 383. The U.S. Surveyor Generals Notes State: Set basalt stone 18x16x12, in mound of stone for 1/4 sec. cor.

DIAGRAM

T13S R35E
S19
1/4--
S30
1987
RLS 848

Description of corner evidence found:

In 1960, David Lee of the USFS found the corner stone he states completely above ground, with 1/4 on south corner. Logging activity since 1960 has completely destroyed all evidence.

No accessories are originally established.

The Corner is determined to be lost to logging and is re-established at proportionate measure between the section corners found 1/2 mi. East & West.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 25" in the ground in a circle of stone.

From Which:

A Fir 8" dia., Bears N57°E., 29.8 ft., scribed: 1/4 S19 BT

A Fir 14" dia., Bears S49°E., 23.6 ft., scribed: 1/4 S30 BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, South & East 3 ft. from the corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1963
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson RLS 848
Mt. Vernon Oregon.

On: Sept. 22, 1987

Refer to Map of Survey No. 1013

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 7 day of May, 1988
Robert D. Leggett by _____
(COUNTY OFFICIAL) (DEPUTY)