

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Original corner established in 1881
by Robb & Graden.
Set basalt stone 15x6x6 in mound
of stone from which:
A 18" Pine brs. N41°W 60 lks (39.6')
A 12" Fir brs. N89°E 15 lks (9.9')

Corner # R-9

DIAGRAM

T135 R35E

S20, S21

S29, S28

Description of corner evidence found:

Found stone mound in good condition with 2
unmarked stones of proper size in center. Held
center of mound as corner location.

30" Ponderosa Pine brs. N41°W 39.6' with visible
scribes. (Original BT)

Dead, down and decomposed NE BT. Root hole
brs. N89°E 9.9'

Description of monument and accessories | established to perpetuate the
original location of this corner:

Set 2 1/2" x 30" aluminum pipe with 3" Aluminum cap
rising 24" in stone mound.

New BTs:

A 6" Mountain Mahogany brs. N17°E 22.5'
marked T135 R35E S21 BT.

A 9" Lodgepole Pine brs. S70°E 32.4'
marked T135 R35E S28 BT.

A 9" Lodgepole Pine brs. S26°W 38.9'
marked T135 R35E S29 BT.

Cap marked

T135 R35E

S20, S21

S29, S28

1986

LS1020

I hereby certify the above corner point was
perpetuated as described in June, 1986, U.S.F.S.
bearing tree signs were placed on all BTs and
a 6" red band was painted around each BT.

Office of.....Surveyor..... County of.....Larimer.....

State of.....OREGON....., I hereby certify that the within instrument was filed in this office

for record on the 3 day of Sept, 1986

Robert D. Ragot by

(COUNTY OFFICIAL)

(DEPUTY)

REGISTERED
PROFESSIONAL
LAND SURVEYOR

GEORGE W. COLVIN, JR.
FEBRUARY 14 1975
1020

Form R6-7100-57 (9/71)

☆ U.S. GOVERNMENT PRINTING OFFICE - 1983-793-276

MAP OF SURVEY NO. _____

R-9