

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. S-1

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T13S
R34E R35E
N1/16
S251S30
1987
RLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 20" in the ground and raised a mound of stone around the pipe.

From Which:

A Mohogany 6" dia., Bears S63°W., 7.1 ft., scribed: N1/16 S25 BT

A Mohogany 5" dia., Bears S52°E., 9.7 ft., scribed: N1/16 S30 BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, South 3 ft. & East 2 ft. from the corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1933
DOUGLAS M. FERGUSON
848

This work is performed by:

Douglas M. Ferguson RLS 848

Mt. Vernon Oregon.

On: Sept. 22, 1987

Refer to Map of Survey No. 1013

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 7 day of May, 1988
Robert D. B. [Signature] by _____
(COUNTY OFFICIAL) (DEPUTY)