

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. **S-3**

History of original corner establishment:

Grant County Survey Records show no previous establishment of this Cor.

DIAGRAM

T13S R35E
C
N1/16:530
C
1987
RLS 848

Description of corner evidence found:

Grant County Survey Records show no previous establishment of this Cor.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 27" in the ground.

From Which:

A Fir 8" dia., Bears S83°E., 2.7 ft., scribed: CN 1/16 S30 BT

A Fir 10" dia., Bears N 4°E., 14.4 ft., scribed: CN 1/16 S30 BT

Measurements to trees taken with a metal tape and magnetic compass, with Declination set off 20 deg. East.

Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, North 2 ft., South 1 ft., and West 3 ft., No Forest Boundary Sign on West post.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1959
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson RLS 848
Mt. Vernon Oregon.
On: Sept. 3, 1987
Refer to Map of Survey No. 1013

Office of.....*Surveyor*..... County of.....*Grant*.....
State of.....*Oregon*....., I hereby certify that the within instrument was filed in this office
for record on the.....*7* day of.....*May*....., 19.....*88*
.....*Robert D. Baggett*..... by.....
(COUNTY OFFICIAL) (DEPUTY)