

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

*Original corner established in 1881
by Robb & Graden;
Set basalt stone 14x10x7 in mound
of stone from which;
A 32" Fir brs. S 32° E 18 lks. (11.9')*

Corner # T-5

DIAGRAM

T135 R35E

1/4

S 30 | S 29

Description of corner evidence found:

*Found 11"x9"x6" stone in center of stone mound with
1/4 marked on North face.*

*Large dead and down Fir marked "1/4 S BT" Southeast
of corner position. Tree slid downhill when falling
and obliterated root position.*

Description of monument and accessories | established to perpetuate the
original location of this corner:

*Set 2 1/2" x 30" aluminum pipe with 3" aluminum cap
rising 10" in stone mound. Buried original stone
alongside.*

Cap marked

New BTs:

*A 9" Fir brs. N 78° E 14.1'
marked 1/4 S 29 BT.*

*A 6" Fir brs. S 20° W 7.7'
marked 1/4 S 30 BT.*

T135 R35E

1/4

S 30 | S 29

1986

LS1020

*I hereby certify the above corner point was
perpetuated as described in June, 1986. U.S.F.S.
Bearing tree signs were placed on all BTs and
a 6" red band was painted around each BT.*

Office of Surveyor County of Garrett

State of OREGON, I hereby certify that the within instrument was filed in this office

for record on the 3 day of Sept, 1986

Robert D. Garrett
(COUNTY OFFICIAL)

by _____
(DEPUTY)

REGISTERED
PROFESSIONAL
LAND SURVEYOR

George W. Colvin, Jr.
OREGON
FEBRUARY 14, 1975
GEORGE W. COLVIN, JR.
1020