

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. V-1

History of original corner establishment:

Corner was originally established by John B. David, in June 1869, under General Land Office Contract No. 131. The U.S. Surveyor Generals Notes State: (Running South on the East Bdry of Section 25, T.13S., R.34E.,) 80 Ch. Set stone 16x13x8 for corner to secs. 30, 31, 25 & 36. In 1881, Bamford Robb, under General Land Office Contract No. 383 made a retracement of the West Exterior of T.13S., R.35E, Surveyor Generals Notes for that Retracement, State: The cor. to sec. 25, 36, 30 & 31, a stone, Repired cor. by building mound of Stone.

DIAGRAM

T13S
R34E R35E
S25 S30
-.-
S36 S31
1987
RLS 848

Description of corner evidence found:

Found an old stone mound with 18"x12"x10" stone in the center of the mound. There are no marks apparently visible, however John B. David, the original Surveyor did not mark his stones very well. Since the stone mound looks original, as constructed by Bamford Robb, in a retracement of that line, the center of the stone mound is accepted as the corner position.

Description of monument and accessories | established to perpetuate the

original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 15" in the ground, set the original stone North alongside and raised a mound of stone around the pipe.

From Which:

A Pine 14" dia., Bears N45°W., 82.2 ft., scribed: T13S R34E S25 BT

A Pine 16" dia., Bears N33°E., 58.0 ft., scribed: T13S R35E S30 BT

A Pine 20" dia., Bears S69°E., 104.5 ft., scribed: T13S R35E S31 BT

5/8"x30" iron pin with plastic cap marked SURVEY MARKER PLS 848, Bears S45°W., 8.9 ft. for Section 36 accessories.

Measurements to accessories taken with a metal tape and magnetic compass. with Declination set off 20 deg. East.

Nailed a brass washer stamped RLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, North 3 ft. & East 4 ft. from the corner.

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

OREGON
JULY 12, 1969
DOUGLAS M. FERGUSON
848

This work is performed by:
Douglas M. Ferguson RLS 848
Mt. Vernon Oregon.
On: Sept. 2, 1987
Refer to Map of Survey No. 1013

Office of..... Surveyor County of..... Grant
State of..... Oregon, I hereby certify that the within instrument was filed in this office
for record on the..... 7..... day of..... May, 19..... 88
..... Ruben P. Baggett by
(COUNTY OFFICIAL) (DEPUTY)