CORNER RESTORATION

CORNER: SW SEC. 6 TWP. 13 S. RANGE 33 E.

ORIGINAL SURVEY BY: John B. David

CONTRACT NUMBER: 131

CONTRACT DATE: June 8, 1869



ORIGINAL DESCRIPTION:
Set Stone 30X17X10 for corner to secs 6, 7, 1 & 12

RESTORATION BY, STAMP AND DATE:
R.D. Bagett, PLS

RECEIVED AND FILED

June 27, 2007
OFFICE OF COUNTY SURVEYOR
Robert D Bagett

ATTEST: Jason L Hayford

REGISTERED PROFESSIONAL LAND SURVEYOR
Robert D. Bagett
OREGON
JULY 12, 1983
ROBERT D. BAGETT
598
Renewal Date 12/31/07

June 23, 2007 Grant County Surveyor

EVIDENCE FOUND: Found a conglomerate stone 30X17X10 marked with 5 grooves on the South edge. Stone was at the East edge of a mound of stone. I accept the position of the marked stone for the section corner.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:
Show how trees are scribed and basis of bearings including compass var.
At the corner point: I set a 1½"x30" galv. iron pipe, 20" in the ground, with attached Grant County Surveyor brass cap marked as shown.

From which I SET NEW REFERENCE POINTS:
A 5/8"x30" iron pin, bears N70°E., 25.25 ft. in a N-S fence with a 2" attached alum. cap marked GRANT COUNTY SURVEYOR RP 1 2007.
A 5/8"x30" iron pin, bears S24°E, 29.20 ft., with 2" attached alum. cap marked GRANT COUNTY SURVEYOR RP 2 2007.
A 5/8"x30" iron pin, bears S70°W, 22.66 ft., with 2" attached alum. cap marked GRANT COUNTY SURVEYOR RP 3 2007.
A 5/8"x30" iron pin, bears N24°W, 26.97 ft. in an E-W fence, with 2" attached alum. cap marked GRANT COUNTY SURVEYOR RP 4 2007.

GRANT COUNTY
T13S
R32E | R33E
S1 | S6
S12 | S7
2007
PLS 598
SURVEYOR

Buried marked corner stone west and alongside iron pipe. Raised a mound of stone 4 ft. base to top of cap. Used mag. compass with 17°E variation and a steel tape to measure RP's.