CORNER RESTORATION

CORNER S.E. Cor. Sec. 1 TWP 13 S. RANGE 33 & 34 E.



ORIGINAL SURVEY BY: John B. David Deputy Surveyor

CONTRACT NUMBER: 131

CONTRACT DATE: June 8, 1869

ORIGINAL DESCRIPTION:

From the corner to T. 12 & 13 S., R. 33 & 34 E., ran South on the West Boundary of Sec. 6;
40.00 Set stone 16"x10"x8" for ¼ Sec. Corner;
80.00 Set stone 17"x9"x8" for corner to Sec. 6,7,1 &12

RESTORATION BY, STAMP AND DATE:

REGISTERED PROFESSIONAL LAND SURVEYOR
Robert D. Bagett
OREGON JULY 12, 1963 ROBERT D. BAGETT 598

BAGETT, GRIFFITH & FERGUSON
170 S. DAYTON - PH. 575-1231
JOHN DAY, OREGON 97845

June 6, 1972

EVIDENCE FOUND:

Found stone 17"x9"x8" in a mound of stone, set 10 ins. in the ground; 3 notches on the South and 1 notch on the North.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:
Show how trees are scribed and basis of bearings, including compass var.

Set 1¼"x30" galvanized iron pipe with Brass Cap marked as shown. Erected a mound of stone 2 feet in diameter around the pipe. The original stone is buried to the East and along side of the pipe. No Bearing Trees were available in the area.

MONUMENT MARKED
COUNTY
T13S
R33E | R34E
S.1 | S. 6
S.12 | S. 7
1972
LS 598
GRANT
SURVEYOR

RECEIVED AND FILED
JUN 8 1972
JOAN LIVEIRA County Clerk
By ..... Deputy

Compass Var. is 20° East

Complete and File with Office of the Grant County Surveyor, Grant County, Oregon, Courthouse, Canyon City, Oregon 97820

E-25