


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by Mark A. Fullerton under
General Land Office Contract No. 395 dated
May 25, 1881.

Surveyor General's records state:
North on line between sec's 20 & 21
80.00 Set basalt stone 16X10X4 in stone mound
for cor. to sec's 16, 17, 20 & 21



F.B.5 P.56 & 57
N-9

Description of corner evidence found:

At assumed corner location found basalt stone 16"X10"X4" (6" at stone center) firmly in earth cast 4 inches deep in West side of stone ring consisting of 6 other large basalt stones 3 foot diameter. Examined stone carefully, stone has numerous lines most apparently natural and was unable to clearly distinguish markings. Stone ring found was similar in nature to that found at 1/4 corner to Sections 20 and 21 to South. Corner fell in center of a natural opening in pine grove which probably accounts for lack of original BT's. Much surface stone is present in corner vicinity. Accept as corner because: (1) stone record size; (2) stone ring appeared man-made; (3) stone in stone ring harmoniously related to corners found North and South; (4) possible markings on stone; (5) stone ring similar to that found at 1/4 corner to South.

Description of monument and accessories | established to perpetuate the original location of this corner:

At position of original stone in West side of stone ring, set 2 1/2 inch O.D. aluminum pipe 30 inches long 16 inches in ground to bedrock with 3 1/4 inch aluminum cap marked as shown:

Marked new bearing trees:

a 9" Juniper bears North 42°00' East, 74.7 ft.,
scribed-T14SR26ES16BT;
a 14" Juniper bears South 27°30' East, 12.2 ft.,
scribed-T14SR26ES21BT;
a 12" double Juniper bears South 42°30' West, 10.6 ft., M.V.18°30'E.
scribed-T14SR26ES20BT;
an 11" Ponderosa Pine bears North 20°15' West, 69.7 ft.,
scribed-T14SR26ES17BT.


Deposited original stone South of cap and raised stone mound 4 foot diameter to cap. Painted red band and faces red and nailed signs 54-3 and 54-4 to new bearing trees.

Set steel post 5 feet North with sign 54-4 facing corner. Nailed brass washer stamped-AS&E LS1026-to face of new bearing trees.

I hereby certify the above corner monument was re-established as herein described on September 3, 1984.

Witnesses: David B. Armstrong
Lynn Bruno

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 23 day of Nov, 1984
Robert D. Smith by _____
(COUNTY OFFICIAL) (DEPUTY)



REGISTERED
PROFESSIONAL
LAND SURVEYOR

David B. Armstrong
10/16/84 OREGON
AUGUST 22, 1975
DAVID B. ARMSTRONG
1026