

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. C-23

History of original corner establishment:

None. Corner established this survey.

DIAGRAM
T14S R27E
C1/4
•
S1
1993
PLS 2405

Description of Corner Evidence Found:

None. Corner established this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2-1/2"x30" aluminum pipe with 3-1/4" aluminum cap, stamped as shown in the DIAGRAM, 12" in the ground and raised a mound of stone around the monument.

From Which:

Ponderosa Pine, 24" dia., bears N67°18'W, 60.8 ft., scribed: C1/4 S1 BT
Ponderosa Pine, 12" dia., bears N44°11'E, 75.7 ft., scribed: C1/4 S1 BT
Ponderosa Pine, 10" dia., bears S40°26'E, 34.7 ft., scribed: C1/4 S1 BT
White Fir, 10" dia., bears S46°18'W, 54.6 ft., scribed: C1/4 S1 BT

Measurements to BT's taken with an Electronic Tacheometer with bearings based on the survey control network. Set steel fence post with Land Survey Monument (54-9) sign 5' north of the monument. Nailed a brass washer stamped PLS 2405 on blaze above BT scribe as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument (54-9) signs on back of each tree as required. Painted a 6" red band above Bearing Trees signs.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 26, 1989

SUSAN E. NEWSTETTER
2405

This work was performed by:
Susan E. Newstetter PLS 2405
Witnessed by: Rick Saul, Brad
Cates and D. Mitchell Ferguson
July 29, 1993
Refer to Grant Co. Survey No.: 1279

Renewal Date: 12/31/94

Office of Surveyor County of Grant
State of OR I hereby certify that the within instrument was
filed in this office for record on the 2 day of Jan, 1994
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)