

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. E-20

History of original corner establishment:

None. Corner established this survey.

DIAGRAM
T14S R27E
S 2
E1/16—
S11
1993
PLS 2405

Description of Corner Evidence Found:

None. Corner established this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2-1/2"x30" aluminum pipe with 3-1/4" aluminum cap, stamped as shown in the DIAGRAM, 20" in the ground and raised a mound of stone around the monument.

From Which:

White Fir, 12" dia., bears N55°31'E, 8.0 ft., scribed: E1/16 S2 BT
White Fir, 16" dia., bears S13°08'W, 10.8 ft., scribed: E1/16 S11 BT

Measurements to BT's taken with an Electronic Tacheometer with bearings based on the survey control network. Set steel fence post with Land Survey Monument (54-9) and Property Boundary (54-2) signs 5' north and south of the monument. Nailed a brass washer stamped PLS 2405 on blaze above BT scribe as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument (54-9) signs on back of each tree as required. Painted a 6" red band above Bearing Trees signs.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 28, 1989
SUSAN E. NEWSTETTER
2405

Renewal Date: 12/3/94

This work was performed by:
Susan E. Newstetter PLS 2405
Witnessed by: Rick Saul, Brad
Cates and D. Mitchell Ferguson
July 27, 1993
Refer to Grant Co. Survey No.: 1279

Office of Surveyor County of Grant
State of OR hereby certify that the within instrument was
filed in this office for record on the 21 day of Jan, 1994
Robert D. Bager by _____
(COUNTY OFFICIAL) (DEPUTY)