

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. F-21

History of original corner establishment:

None. Corner established this survey.

DIAGRAM
T14S R27E
N 1/16
S11|S12
1993
PLS 2405

Description of Corner Evidence Found:

None. Corner established this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2-1/2"x30" aluminum pipe with 3-1/4" aluminum cap, stamped as shown in the DIAGRAM, 26" in the ground.

From Which:

White Fir, 22" dia., bears N47°34'W, 80.0 ft., scribed: N1/16 S11 BT
White Fir, 16" dia., bears N39°49'E, 47.6 ft., scribed: N1/16 S12 BT

Measurements to BT's taken with an Electronic Tacheometer with bearings based on the survey control network. Set steel fence post with Land Survey Monument (54-9) and Property Boundary (54-2) signs 5' north and west of the monument. Nailed a brass washer stamped PLS 2405 on blaze above BT scribe as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument (54-9) signs on back of each tree as required. Painted a 6" red band above Bearing Trees signs.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 26, 1989
SUSAN E. NEWSTETTER
2405

This work was performed by:
Susan E. Newstetter PLS 2405
Witnessed by: Rick Saul, Brad
Cates and D. Mitchell Ferguson
July 27, 1993
Refer to Grant Co. Survey No.: 1279

Office of Surveyor County of Grant
State of OR I hereby certify that the within instrument was
filed in this office for record on the 21 day of Jan, 1992
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)