


CORNER RESTORATION

CE 1/16 cor.
Sec. 1 TWP 14 S RANGE 30 E
CORNER _____

ORIGINAL SURVEY BY:

CONTRACT NUMBER:

CONTRACT DATE:



ORIGINAL DESCRIPTION:
No previous monument established of record.

RESTORATION BY, STAMP AND DATE:

R.D. Bagett
J.L. Watson
K.J. Workman

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Bagett

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

RECEIVED AND
FILED

APR 25 1989

OFFICE OF COUNTY SURVEYOR
Robert D. Bagett
Attest: _____

March 14, 1989

EVIDENCE FOUND: None

SEE RECORD MAP OF SURVEY NO. 1071

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED: Show how trees are scribed and basis of bearings, including compass var.

At the midpoint, and on line between the center 1/4 corner position and the E 1/4 corner of Section 1, I set a 5/8" iron pin with attached 1-1/2" alum. cap marked as shown, from which I scribe NEW BEARING TREES:
A juniper 8 inches diam. bears N.63°E., 76.4 feet, marked CE 1/16 S1 BT.
A juniper 8 inches diam. bears S.46°E., 143.0 feet, marked CE 1/16 S1 BT.

Used true bearings and Mac II EDM for measurements to BTs. I measured to a 50d nail driven in the side center at the root crown of the BTs. Attached BT tags to bearing trees.

MONUMENT MARKED

