


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:


Original corner established by: S. W. Lackland , Deputy Surveyor,
under Contract No. 357, dated July 2, 1880.

Surveyor General Record States: Set stone 20x9x4 inches in mound of
stone for 1/4 section corner.



Description of corner evidence found:

Found stone 21x9x7 inches, marked "1/4 S", lying in a rock jack at
the corner of fences running south and west.



See Land Partition Plat No. 2003-4

Description of monument and accessories set at corner location:

I accept the fence corner as the best evidence of the position of the 1/4 corner. I set a 2½"x30"
aluminum pipe with attached 3" aluminum cap, 26 inches in the ground. Placed original marked
stone north alongside pipe. The cap is stamped as shown in the diagram.

From which:

A 10" Juniper bears South, 21.25 feet, marked 1/4S9BT.

A 5/8"x30" iron pin bears N50°E, 12.13 feet, with attached red plastic cap
marked CORNERSTONE SURVEYING INC.

A 5/8"x30" iron pin bears S42°E, 10.60 feet, with attached red plastic cap
marked CORNERSTONE SURVEYING INC.

A 5/8"x30" iron pin bears N42°W, 14.00 feet, with attached red plastic cap
marked CORNERSTONE SURVEYING INC.

I used a steel tape measuring to a 50d nail driven in the side center at the root crown of the BT
and magnetic compass, with 18° E. declination.

Date: April 23, 2003

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 30 day of MAY, 2003.
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)