


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:


Original corner established by: S. W. Lackland , Deputy Surveyor,
under Contract No. 357, dated July 2, 1880.

Surveyor General Record States: Set stone 14x8x8 in mound of stone
for 1/4 section corner.



Description of corner evidence found:

No evidence of the original corner was found.



See Land Partition Plat No. 2003-4

Description of monument and accessories set at corner location:

At the point determined by single proportionate measure, I set a 2½"x30" aluminum pipe with
attached 3" aluminum cap, 26 inches in the ground, surrounded by a mound of stone. The cap is
stamped as shown in the diagram.

From which:

A 12" Juniper bears N45°E, 123.5 feet, marked 1/4S9BT.

A 7" Juniper bears S55°W, 39.8 feet, marked 1/4S8BT.

A 5/8"x30" iron pin bears N04°W, 15.38 feet, with attached red plastic cap
marked CORNERSTONE SURVEYING INC.

A 5/8"x30" iron pin bears S44°E, 18.85 feet, with attached red plastic cap
marked CORNERSTONE SURVEYING INC.

I used a steel tape measuring to a 50d nail driven in the side center at the root crown of the BT's
and magnetic compass, with 18° E. declination.

Date: April 16, 2003

Office of Surveyor County of Grant
State of Oregon I hereby certify that the within instrument was filed in this office
for record on the 30 day of MAY, 2003.
Robert D. Bazzell by _____
(COUNTY OFFICIAL) (DEPUTY)