


CORNER RESTORATION

CORNER SW cor.
Sec. 12 TWP 14 S RANGE 30 E
ORIGINAL SURVEY BY: S.W. Lackland
CONTRACT NUMBER: 357
CONTRACT DATE: July 2, 1880



ORIGINAL DESCRIPTION: Set stone 14x8x6 in mound of stone for corner to Sections 11, 12, 13 & 14.

RESTORATION BY, STAMP AND DATE:

R.D. Bagett
J.L. Watson
K.J. Workman

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Bagett

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

RECEIVED AND
FILED

APR 25 1989

OFFICE OF COUNTY SURVEYOR
Robert D. Bagett
Attest:

March 13, 1989

EVIDENCE FOUND: Small mound of stone at corner of the remains of ancient fences running north-south and west. This position is harmoniously related to other known corners in this area. I accept the location of this fence corner as the best available evidence of the section corner position.

SEE RECORD MAP OF SURVEY NO. 1071

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:


Show how trees are scribed and basis of bearings, including compass var.

At the corner point: Set a 5/8"x30" iron pin, with attached 1-1/2" alum. cap marked as shown:

Raised a mound of stone 4 foot base to top of cap.

No corner accessories taken.

MONUMENT MARKED



J-21
See Remon Dated April, 1991