


CORNER RESTORATION

CORNER: CN 1/16TH SEC. 23, TWP. 14 S., RANGE 30 E., W.M.

ORIGINAL SURVEY BY: CORNER NOT

CONTRACT NUMBER: PREVIOUSLY

CONTRACT DATE: ESTABLISHED



ORIGINAL DESCRIPTION: NONE


RESTORATION BY, STAMP AND DATE:


Jason L. Hatfield, PLS
Michael C. Springer, PLS

RECEIVED AND FILED
GRANT COUNTY SURVEYOR

AUG 01 2011

July 7, 2011

BY: 




See Record Map of Survey No. 1927

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

At the corner point as located by survey, set a 5/8"x30" iron pin 29" in ground, with attached 2" diameter aluminum cap marked as shown.

From which, I SET THE FOLLOWING REFERENCE POINT:

- ▶ A 5/8"x30" iron pin bears N52°W, 27.7 ft., with attached yellow plastic cap marked "BENCHMARK SURVEYING"
- ▶ A 5/8"x30" iron pin bears S62°07'W, 51.83 ft., with attached yellow plastic cap marked "BENCHMARK SURVEYING"



Used RTK GPS to measure the RP's. Bearings are based on Record Map of Survey No. 1927.