


CORNER RESTORATION

CORNER: CW 1/16 SEC. 23, TWP. 14 S., RANGE 30 E., W.M.

ORIGINAL SURVEY BY: Michael Spears, Grant County Surveyor

SURVEY NUMBER: 6S, Survey Record Book 1, Page15

DATE: October 1, 1908




ORIGINAL DESCRIPTION: *Rock w/ Pine Bears N62°E 45 lks*


RESTORATION BY, STAMP AND DATE:

Jason L. Hatfield, PLS
Michael C. Springer, PLS

RECEIVED AND FILED
GRANT COUNTY SURVEYOR

AUG 01 2011

BY: 



July 7, 2011

See Record Map of Survey No. 1927

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:


I found no remaining evidence of Spears' stone or the pine bearing tree. This area has been logged since 1908. I declare this corner lost, and reestablish its position by survey. At the corner point, we set a 5/8"x30" iron pin 28" in the ground, with attached 2" diameter aluminum cap marked as shown.

From which, I SET THE FOLLOWING REFERENCE POINT:

- ▶ A 5/8"x30" iron pin bears N59°08'W, 31.87 ft., with attached yellow plastic cap marked "BENCHMARK SURVEYING", set in a North-South fence..

I also SCRIBED A BEARING TREE:

- ▶ A 9.5" DBH ponderosa pine bears N70°E, 0.85 feet marked CW1/16 S23 BT.



Used a total station to measure the accessories. The distance to the bearing tree was measured to a 50d nail driven into the side center at the root crown of the tree. Attached a yellow aluminum Bearing Tree tag to the tree. Bearings are based on Record Map of Survey No. 1927.