

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established

DIAGRAM

T14S R30E
 N1/16
 |
 S26.525
 |
 1983
 PLS 848

Description of corner evidence found:

Corner not previously established

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 2-1/2" aluminum cap, stamped as shown on the DIAGRAM, set 14" in the ground and raised a mound of stone and earth around the pipe.

From Which:

A Pine 10" dia. Bears N33E, 5.4 ft., scribed N1/16 S 25 BT

A Pine 12" dia. Bears S54W, 26.4 ft., scribed N1/16 S 26 BT

Set steel fence posts with Warning and Boundary signs North and East approx. 5 ft. from Cor.

Nailed brass washers stamped PLS 848, Bearing Tree signs and Warning signs to each tree.

Painted a 6" red band around each tree.

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

OREGON
 JULY 12, 1969
 DOUGLAS M. FERGUSON
 848

Corner Monumented Nov. 7, 1983
 Witnessed by Dan Martin

Office of Surveyor County of Grant
 State of Oregon I hereby certify that the within instrument was filed in this office
 for record on the 12 day of April, 1984
Robert D. Boyer by _____
 (COUNTY OFFICIAL) (DEPUTY)