

CERTIFIED RECORD OF LAND CORNER MONUMENTATION**History of original corner establishment:**

Corner established in 1880, by S.W. Lackland, under General Land Office Contract No. 357. Surveyor Generals Notes State: Set Stone 30x20x18 in mound of stone for 1/4 Sec Cor.

DIAGRAM

T14S R30E
1/4
|
S26.S25
|
1983
PLS 848

Description of corner evidence found:

No Evidence Found, Corner falls on a steep West slope, on nearly solid rock, the corner stone and mound have apparantly rolled down the slope. Set Cor By Proportion from found Section Corners 1/2 mi. North and 1/2 mi. South from this Cor.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 2-1/2" aluminum cap, stamped as shown on the DIAGRAM, set 16" in the ground and raised a mound of stone around pipe.

From Which;



A Pine 8" dia. Bears N 6E, 36.0 ft., scribed 1/4S25 BT

A Pine 20" dia. Bears S36W, 10.6 ft., scribed 1/4S26 BT

Set steel fence posts North 5 ft. and East 5 ft. from Cor.

Nailed brass washers stamped PLS 848, Bearing Tree signs and Warning signs to each tree.

Painted a 6" red band around each tree.



Corner Monumented Nov. 14, 1983
Witnessed by Dan Martin

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 12 day of April, 1984
Robert D. Dugan by _____
(COUNTY OFFICIAL) (DEPUTY)