


CORNER RESTORATION

CORNER: SW1/16 SEC. 1 TWP. 14 S. RANGE 31 E.

ORIGINAL SURVEY BY: Michael Spears,
Grant County Surveyor

ORIGINAL SURVEY: 1912 Survey recorded in
Grant County Survey Book 1,
Pages 65-66



ORIGINAL DESCRIPTION:

Michael Spears, Grant Count Surveyor, set a 2" diameter iron pipe at this corner in a 1912 survey described in Grant County Surveyor Book 1, Pages 65 through 66.


RESTORATION BY, STAMP AND DATE:

M.C. Springer, PLS
J.L. Hatfield, LSIT

RECEIVED AND
FILED



July 20, 2006
OFFICE OF COUNTY SURVEYOR
Robert D. Bayett
ATTEST: *James L. Hatfield*



July 7, 2006

EVIDENCE FOUND:

After a diligent search, I found no remains of Spears' pipe. I found monuments at the S1/16 between sections 1 and 2, and at the CW1/16 of Section 1, which were both set by Spears in his 1912 survey. I establish the position of this corner by a distance-distance intersect, holding Spears' record distances. The position for this 1/16 corner has been perpetuated by a distance-distance intersection since 1980 and has been relied upon by landowners since Spears' 1912 survey.

See Record Map of Survey No. 1765

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:


Show how trees are scribed and basis of bearings including compass var.

At the corner point: I set a 5/8"x30" iron pin, 6" in the ground, with attached 1 1/2" alum. cap marked as shown. I built a 3 ft. mound of stone around the pin.

From which I SET NEW REFERENCE POINTS:

A 5/8"x30" iron pin bears S86°19'W, 9.51 ft. with attached yellow plastic cap marked BGB Survey Marker

A 5/8"x30" iron pin bears N48°48'W, 17.25 ft.
with attached yellow plastic cap marked BGB Survey Marker



Used GPS RTK to measure to the RP's, Raised a mound of stone 3ft. base to top of the cap.