


CORNER RESTORATION

CORNER: CS1/16 SEC. 1 TWP. 14 S. RANGE 31 E.

ORIGINAL SURVEY BY: Corner Not

CONTRACT NUMBER: Previously

CONTRACT DATE: Established



ORIGINAL DESCRIPTION: None

RESTORATION BY, STAMP AND DATE:

M.C. Springer, PLS
J.L. Hatfield, LSIT

RECEIVED AND
FILED

July 20, 2006
OFFICE OF COUNTY SURVEYOR
Robert D. Long
ATTEST: *[Signature]*



July 7, 2006

EVIDENCE FOUND: None

See Record Map of Survey No. 1765

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:


Show how trees are scribed and basis of bearings including compass var.

At the corner point: I set a 5/8"x30" iron pin, 30" in the ground, with attached 1½" alum. cap marked as shown.

From which I SCRIBE NEW BEARING TREES:

A Ponderosa Pine 17" diam., bears S35°W, 6.5 ft.
marked CS1/16 S1 BT.

A Ponderosa Pine 19" diam., bears N17°W, 47.7 ft.
marked CS1/16 S1 BT.



Used mag. compass with 17° var. and steel tape, measuring to a 50d nail driven in the side-center at the root crown of the BT's. Attached BT tags to BT's.