


CORNER RESTORATION

CORNER: NW CORNER SEC. 17 TWP. 14 S. RANGE 31 E., W.M.

ORIGINAL SURVEY BY: Bamford Robb, Deputy U.S. Surveyor

CONTRACT NUMBER: 357

CONTRACT DATE: July 2, 1880



ORIGINAL DESCRIPTION: Set Stone 12X10X8 in mound of stone for cor. to secs. 7, 8, 17 & 18.

RESTORATION BY, STAMP AND DATE:

J.L. Hatfield, PLS



Benchmark Land Surveying
217 N. Canyon Blvd.
John Day, OR 97845

May 15, 2012

RECEIVED AND FILED
GRANT COUNTY SURVEYOR

JUN 01 2012

BY: 



See Record Map of Survey No. 1949

EVIDENCE FOUND: We did not find the original corner stone. I utilized the long established east-west fence line for northings, and a proportionate easting position, measuring between the found monument at the North 1/4 Corner Section 18 and the established monument at the North 1/4 Corner Section 17.

DESCRIPTION OF MONUMENT AND ACCESSORIES:

At the corner point, I set a 1½"x30" galvanized iron pipe with attached 2½" brass cap 26" in the ground. Raised a 2 foot diameter mound of stone to top of cap. Brass cap is marked as shown below.

From which, I SET REFERENCE POINTS:

- ▶ A 5/8"x30" iron pin bears N.45°59'E., 17.78 ft., with attached yellow plastic cap marked "BENCHMARK SURVEYING"
- ▶ A 5/8"x30" iron pin bears S.43°19'E., 30.80 ft., with attached yellow plastic cap marked "BENCHMARK SURVEYING"
- ▶ A 5/8"x30" iron pin bears S.45°01'W., 28.55 ft., with attached yellow plastic cap marked "BENCHMARK SURVEYING"
- ▶ A 5/8"x30" iron pin bears N.45°31'W., 31.16 ft., with attached yellow plastic cap marked "BENCHMARK SURVEYING"



Used RTK GPS to measure RP's. Bearings are based on Map of Survey No. 1949.