


CORNER RESTORATION

CORNER: S1/16 CORNER SEC. 17 TWP. 14 S. RANGE 31 E., W.M.

ORIGINAL SURVEY BY: CORNER NOT

CONTRACT NUMBER: PREVIOUSLY

CONTRACT DATE: ESTABLISHED



ORIGINAL DESCRIPTION: NONE


RESTORATION BY, STAMP AND DATE:

J.L. Hatfield, PLS

RECEIVED AND FILED
GRANT COUNTY SURVEYOR

JUN 01 2012

BY: 



Benchmark Land Surveying
217 N. Canyon Blvd.
John Day, OR 97845

May 23, 2012

See Record Map of Survey No. 1949

EVIDENCE FOUND: NONE

DESCRIPTION OF MONUMENT AND ACCESSORIES:

At the corner point, I set a 5/8"x30" iron pin with attached 2" aluminum cap 28" in the ground. Raised a small mound of stone to top of cap. Aluminum cap is marked as shown below.

From which, I SET REFERENCE POINTS:

- ▶ A 5/8"x30" iron pin bears S.69°38'E., 18.87 ft., with attached yellow plastic cap marked "BENCHMARK SURVEYING".
- ▶ A 5/8"x30" iron pin bears N.67°30'W., 22.82 ft., with attached yellow plastic cap marked "BENCHMARK SURVEYING".

