


CORNER RESTORATION

CORNER: CS1/16 CORNER SEC. 17 TWP. 14 S. RANGE 31 E., W.M.

ORIGINAL SURVEY BY: CORNER NOT

CONTRACT NUMBER: PREVIOUSLY

CONTRACT DATE: ESTABLISHED



ORIGINAL DESCRIPTION: NONE

RESTORATION BY, STAMP AND DATE:

J.L. Hatfield, PLS


Benchmark Land Surveying
217 N. Canyon Blvd.
John Day, OR 97845

May 23, 2012

RECEIVED AND FILED
GRANT COUNTY SURVEYOR

JUN 01 2012

BY:



See Record Map of Survey No. 1949

EVIDENCE FOUND: NONE

DESCRIPTION OF MONUMENT AND ACCESSORIES:

At the corner point, I set a 5/8"x30" iron pin with attached 2" aluminum cap 28" in the ground. Raised a small mound of stone to top of cap. Aluminum cap is marked as shown below.

From which, I SET REFERENCE POINTS:

- ▶ A 5/8"x30" iron pin bears S.60°14'W., 11.94 ft., with attached yellow plastic cap marked "BENCHMARK SURVEYING".
- ▶ A 5/8"x30" iron pin bears N.05°43'W., 26.94 ft., with attached yellow plastic cap marked "BENCHMARK SURVEYING".

