


CORNER RESTORATION

N 1/16 cor. bet.
CORNER Secs. 26&27 TWP 14S RANGE 31E

ORIGINAL SURVEY BY:

CONTRACT NUMBER:

CONTRACT DATE:




ORIGINAL DESCRIPTION:


N 1/16 corner not previously established of record.
I establish this 1/16 corner at mid point and on line between the
NW corner and W $\frac{1}{4}$ corner of the section.

RESTORATION BY, STAMP AND DATE:

R. D. Bagett
S. F. Jackson
C. Gerega



Robert D. Bagett



July 25, 1978

Grant County Surveyor.

EVIDENCE FOUND:

RECEIVED AND
FILED

John Liveira
AUG 24 1978
JOHN LIVEIRA, County Clerk

By _____ Deputy

See Map of Survey No. 519.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At the corner point: I drove a 5/8" x 30" iron pin 26"
in the ground and surrounded same with a mound of stone to
top of pin.
from which I scribe NEW BEARING TREES:

A 13" pine bears S. 66° W., 5.1 ft., mkd N. 1/16 S. 27 CSBT.

A 12" pine bears N. 11° E., 33.9 ft. mkd. N. 1/16 S. 26 CSBT.

Used compass with 20° East variation, and steel tape measuring
to face of BT blaze.

MONUMENT MARKED

