


CORNER RESTORATION

C.E. 1/16 Cor.
CORNER Sec. 35 TWP 14S., RANGE 31 E., W.M.

ORIGINAL SURVEY BY:

CONTRACT NUMBER:

CONTRACT DATE:



ORIGINAL DESCRIPTION:



The center East 1/16 was established by Michael Spears, County Surveyor, June 26, 1911. Recorded in Surveyors record Book 1, Page 33, which states: I set a rock marked 1/16 CS, from which:

A pine 20" in diam. bears N. 81° E. 44 lins.
A pine 12" in diam. bears S. 7° E. 40 links.

I established the center - East 1/16 corner on line, and halfway between the C ¼ cor. sec. 35 and the E ¼ cor. sec. 35. (Stadia distances)

RESTORATION BY, STAMP AND DATE:

R. D. Bagett
S. L. Crane



RECEIVED AND
FILED

NOV 25 1977
John Liveira
JOHN LIVEIRA, County Clerk
By _____ Deputy
Grant County Surveyor

October 11, 1977

EVIDENCE FOUND:

From the corner point:

Found BT's by Spears:

A standing 30" in diam. pine trunk, clearly marked BT 1/16 bears N. 13° E. 111 feet;
A 22" pine stump and fallen log with healed blaze bears N. 1° E. 76 feet.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED: Show how trees are scribed and basis of bearings, including compass var.

At the corner point I set a 5/8" x 30" iron pin in a mound of stone at the base of a live 18" pine on the N.E. side of tree, from which I tag and scribe New B.T.'s.

A juniper 6" in diam. bears N. 30° W. 18.6 feet, marked CE 1/16 S35 CSBT.
A pine 18" in diam. bears S. 73° W. 0.60 feet, marked CE 1/16 S35CSBT.

I used a compass with 20° East variation and steel tape, measuring to face of blaze on B.T.'s.

Corner is 100 feet South of East-West fence line.

See Map of Survey No. 467.

MONUMENT MARKED

