


CORNER RESTORATION

South $\frac{1}{4}$ Cor.
CORNER Sec. 35 TWP 14 S. RANGE 31 E. W.M.

ORIGINAL SURVEY BY: Bamford Robb

CONTRACT NUMBER: 357

CONTRACT DATE: July 2, 1880



ORIGINAL DESCRIPTION:

S. $89^{\circ} 54'$ W. : on a true line between Secs. 2 & 35.

35.00 Brook 2 lks. wide flows S.E.



40.00 set stone 14x12x6 for $\frac{1}{4}$ Sec. cor., from which:

A pine 30" in diam. bears S. 30° W. 57 lks. dist.

A pine 30" in diam. bears N. 65° W. 91 lks. dist.

RESTORATION BY, STAMP AND DATE:

R. D. Baggett
S. L. Crane



RECEIVED AND
FILED

NOV 25 1977

JOHN LIVEIRA, County Clerk

By _____ Deputy

September 25, 1977

Grant County Surveyor

EVIDENCE FOUND:

I found a 12x10x6 stone marked $\frac{1}{4}$, in a mound of stone in East-West fenceline, from which old B.T.'s,

A 36" pine stump bears N. 65° W. 60.1 feet, no marks visible.

A 26" pine stump bears S. 34° W. 37.6 feet, marked $\frac{1}{4}$ S on trunk that has fallen from stump.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At the corner point I set a $1\frac{1}{2}$ "x30" iron pipe 24" in the ground in a mound of stone with brass cap marked as shown. The original stone is buried North and alongside pipe. From which I scribe and tag new B.T.'s

A fir 14" in diam. bears S. 85° W. 14.8 feet, marked $\frac{1}{4}$ S2 CSBT.

A pine 14" in diam. bears N. 2° E. 29.4 feet, marked $\frac{1}{4}$ S35 CSBT.

I used a compass with 20° East variation and steel tape, measuring to face of blaze on B.T.'s.

Corner 0.6 feet South of East-West fence line.

See Map of Survey No. 467.

MONUMENT MARKED

