


CORNER RESTORATION

CORNER E 1/16 S 2 TWP 14 S., RANGE 31 E., W.M.

ORIGINAL SURVEY BY:

CONTRACT NUMBER:

CONTRACT DATE:




ORIGINAL DESCRIPTION:

Corner not previously established of record.


I established the East 1/16, on line, and halfway between the S $\frac{1}{4}$ cor. Sec. 35 and the S.E. Sec. cor Sec. 35.

RESTORATION BY, STAMP AND DATE.

R. D. Bagett
S. L. Crane



Robert D. Bagett



October 10, 1977

RECEIVED AND
FILED

NOV 25 1977
John Liveira
JOHN LIVEIRA, County Clerk

By _____ Deputy
Grant County Surveyor

EVIDENCE FOUND:

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At the corner point I set a 5/8"x30" iron pin in a mound of stone, from which I scribe and tag New B.T.'s

A Juniper 8" in diam. bears N. 46° W. 18.0 feet, marked E 1/16 S35CSBT.

A Juniper 6" in diam. bears S. 62° W. 16.7 feet, marked E 1/16 S2 CSBT.

I used a compass with 20° East variation and steel tape, measuring to face of blaze on B.T.s.

See Map of Survey No. 467.

MONUMENT MARKED

