


CORNER RESTORATION

S.W. Cor.
CORNER Sec. 36 TWP 14 S. RANGE 31 E.

ORIGINAL SURVEY BY: Banford Robb

CONTRACT NUMBER: 357


CONTRACT DATE: July 2, 1880



ORIGINAL DESCRIPTION:

Set stone 14"x12"x8" in mound of stone for corner to Sections 1, 2, 35, and 36.

RESTORATION BY, STAMP AND DATE:



Robert D. Baggett

JULY 12, 1963
ROBERT D. BAGETT
598

RECEIVED AND
FILED

JAN 10 1972

JOHN LIVEIRA, County Clerk

By _____ Deputy

October 26, 1971

EVIDENCE FOUND:

Found unmarked stone in dim mound of stone, set 3 feet North of fence corner. Fences run East and South, and the remains of an old fence line runs North. Three feet South of corner, a 40" P. pine has been blazed on 3 sides 30 or 40 years ago.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

Set 1 1/2"x30" iron pipe 14" in the ground with brass cap marked as shown. Placed original stone in ground along side pipe and raised a mound of stone around pipe. MONUMENT MARKED

From which a Juniper 7 ins. dia. bears N47°E 1175 feet marked T14S R31E S36 B.T.

A P. pine 42 ins. dia. bears South 2.20 feet marked T15S R31E S1 B.T.

A Juniper 10 ins. dia. bears N8°W 23.40 feet marked T14S R31E S35 B.T.

Measure to 10 penny nail in trees

Used compass var. 20°
Complete and File with Office of the Grant
County Surveyor, Grant County, Oregon,
Courthouse, Canyon City, Oregon 97820

