


CORNER RESTORATION

Sec. 1
 CORNER W. 1/16 Cor. TWP T14S RANGE R32E

ORIGINAL SURVEY BY:

CONTRACT NUMBER:

CONTRACT DATE:



ORIGINAL DESCRIPTION:

No original corner set.

**RECEIVED AND
FILED**

DEC 22 1976
John Liveira
 JOHN LIVEIRA, County Clerk

By _____ Deputy

RESTORATION BY, STAMP AND DATE:

Melvin V. Davenport
 6-5-76
 OREGON
 MAY 9, 1952
 MELVIN V. DAVENPORT
 REGISTERED PROFESSIONAL ENGINEER
 3319

June 5, 1976

EVIDENCE FOUND:

No evidence.

This corner set by single proportionate measure between the 1/4 corner of Sections 1 and 2 and the Center 1/4 corner Sec. 1, T14S R32E W.M.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At the corner point: Set a monument, mounted on a 2"x24" iron pipe, set 18" in the ground, with a brass cap marked as shown.

From which I scribe NEW BEARING TREES:

A fir 7" diam., bears S35°E 6.0 ft., mkd.

X BT. (Leaning Tree).


A fir 6" diam., bears N16°W 24.3 ft., mkd.

CW1/16 S1 BT.

These trees were scribed and tagged by the G.C.S.

I surrounded corner with mound of stone. I used a compass with a 20° east variation and steel tape measuring to face of BT.

MONUMENT MARKED



Complete and File with Office of the Grant
 County Surveyor, Grant County, Oregon,
 Courthouse, Canyon City, Oregon 97820

SEE SURVEY 406

C-22