


CORNER RESTORATION

Sec. 12
CORNER NW 1/16 cor TWP 14S RANGE 32E., W.M.

ORIGINAL SURVEY BY:

CONTRACT NUMBER: NW 1/16 cor. not previously established.

CONTRACT DATE:



ORIGINAL DESCRIPTION:

NW 1/16 cor. not previously established.

RECEIVED AND
FILED

RESTORATION BY, STAMP AND DATE:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

NOV 19 1975
John Liveira
JOHN LIVEIRA, County Clerk
By.....Deputy

Robert D. Bagett
OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

October 23, 1975

Grant County Surveyor

EVIDENCE FOUND:

Not applicable.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

Set a 5/8"x30" iron pin 12" in the ground, and surrounded same with a mound of stone to top of pin. from which I scribe NEW BEARING TREES: **MONUMENT MARKED**

A pine, 28" diam., bears N44°E., 30.7 ft., mkd.
NW 1/16 S12 CSBT.

A fir, 17" diam., bears N29°W., 10.8 ft., mkd.
NW 1/16 S12 CSBT.

Used compass and steel tape, with 20°East var. on compass, measuring to the face of BT blaze.



Complete and File with Office of the Grant
County Surveyor, Grant County, Oregon,
Courthouse, Canyon City, Oregon 97820

SEE MAP OF SURVEY NO. 384.