

CORNER RESTORATION


Sec. 12
Center-North
CORNER 1/16th cor TWP 14S RANGE 32E., W.M.

ORIGINAL SURVEY BY:

CONTRACT NUMBER:

C-N 1/16 not previously established.

CONTRACT DATE:



ORIGINAL DESCRIPTION:

C-N 1/16 cor/ not previously established.

RESTORATION BY, STAMP AND DATE:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Baggett
OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

October 23, 1975

RECEIVED AND
FILED

NOV 10 1975
John Liveira
JOHN LIVEIRA, County Clerk

By, Deputy

Grant County Surveyor

EVIDENCE FOUND:

Not applicable.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.


Set a 5/8"x30" iron pin 12" in the ground, and surrounded same with a mound of stone to top of pin.

MONUMENT MARKED

from which I scribe NEW BEARING TREES:

A pine, 7" diam., bears S.10°W., 17.5 ft., mkd.
CN1/16 S12 CSBT.

A fir, 10" diam., bears N.81°W., 46.6 ft., mkd.
CN1/16 S12 CSBT.



Used compass with 20° East variation and steel tape measuring to the face of the blaze on BTs.
Complete and File with Office of the Grant

County Surveyor, Grant County, Oregon,
Courthouse, Canyon City, Oregon 97820

This cor. is about 12 ft.
east of Bear Gulch Road,
SEE MAP OF SURVEY NO. 384