

CORNER RESTORATION


Center $\frac{1}{4}$ cor.

CORNER Sec. 10 TWP 14 S. RANGE 32 E.

ORIGINAL SURVEY BY:

CONTRACT NUMBER:

CONTRACT DATE:



ORIGINAL DESCRIPTION:

Corner not previously established.

RESTORATION BY, STAMP AND DATE.

R. D. Bagett
W. Gentis

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Bagett

OREGON
JULY 12, 1969
ROBERT D. BAGETT
598

June 29, 1976

Grant County Surveyor

EVIDENCE FOUND:

Established center $\frac{1}{4}$ corner at intersection of lines between opposite corresponding $\frac{1}{4}$ corners.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:


Show how trees are scribed and basis of bearings, including compass var.

At the corner point: set $1\frac{1}{2}$ "x30" iron pipe 20" in the ground in mound of stone with brass cap marked as shown, from which I scribe NEW BT's.

A pine 9" in diam. bears S. 26° E., 7.3 feet marked $C\frac{1}{4}$ S10CSBT
A pine 7" in diam. bears N. 43° E., 18.5 feet marked $C\frac{1}{4}$ S10CSBT

I used a compass with 20° East variation and steel tape measuring to face of blaze.

MONUMENT MARKED



RECEIVED AND
FILED

DEC 20 1976
John Liveira
JOHN LIVEIRA, County Clerk

By.....Deputy