

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Set by B. Robb, contract 357, dated July 2, 1880.
N89° 53' west on true line 40.09 chains set basalt
stone 10x9x5 in a mound of stone for $\frac{1}{4}$ section
corner. From which:

A pine 18in dia bears N40°E 40 LKS dist

DIAGRAM

T14S R33E

$\frac{1}{4}$ 10
15

Description of corner evidence found:

18" PP, Dead and Down, scribed $\frac{1}{4}$ S

Description of monument and accessories I established to perpetuate the original location of this corner:

At S40°W 26.4 ft. from original BT I set a $3\frac{1}{4}$ " aluminum cap on
 $2\frac{1}{2}$ "x30" aluminum pipe 8" above ground.


From which I marked new BT's

A Juniper 10" dia. bears N26°E 49.0 ft. scribed $\frac{1}{4}$ S10 BT

A Juniper 8" dia. bears S80°E 10.7 ft. scribed $\frac{1}{4}$ S15 BT

Bearing and distances to center of tree with variance 20°.
Brass LS disc in lower blaze.

I hereby certify the above corner monument was
re-established as herein described on November 24,
1981.



REGISTERED
PROFESSIONAL
LAND SURVEYOR

David E. Scott

OREGON
JULY 13, 1979
DAVID E. SCOTT
1844

Office of.....SURVEYOR..... County of.....GRANT.....
State of.....OREGON....., I hereby certify that the within instrument was filed in this office
for record on the.....5..... day of.....April....., 1981.....
Robert N. Bayett by.....
(COUNTY OFFICIAL) (DEPUTY)