

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Set by B. Robb, Contract 357, dated July 2, 1880.
 40.08 chains set stone 12x8x6 in mound of stone for $\frac{1}{4}$
 section corner from which:

A pine 12" in dia bears N60°W 198 LKS DIST

A pine 14" in dia bears S40°E 240 LKS DIST

DIAGRAM

T14S	R33E
$\frac{1}{4}$	12 13

Description of corner evidence found:

Found stone marked $\frac{1}{4}$ 10x8x6, found mound of 6 rocks 6x4x3, 8 feet
 east of stone (uphill). Found remains of stump scribed BT N64°W
 129.8 feet from mound.

Description of monument and accessories I established to perpetuate the original location of this corner:


At location of mound I set a $3\frac{1}{4}$ " aluminum cap on $2\frac{1}{2}$ "x30" aluminum pipe.
 18" above ground in mound 4.0'x1.5' marked
 from which I marked new BT's:

A Juniper 8" dia. bears N25°E 43.8 ft. scribed $\frac{1}{4}$ S12 BT

A Juniper 10" dia. bears S47°E 52.3 ft. scribed $\frac{1}{4}$ S13 BT

Bearings and distances to center of tree, 20° variance.

Brass LS 1844 disc in lower blazes.



I hereby certify the above corner monument was
 re-established as herein described on November 10,
 1981.

**REGISTERED
 PROFESSIONAL
 LAND SURVEYOR**

David E. Scott

OREGON
 JULY 13, 1979
DAVID E. SCOTT
 1844

Office of.....SURVEYOR..... County of.....GRANT.....
 State of.....OREGON....., I hereby certify that the within instrument was filed in this office
 for record on the.....5..... day of.....April....., 1982.....
Robert D. Baggett by.....
 (COUNTY OFFICIAL) (DEPUTY)