

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Set by B. Robb, contract 357, dated July 2, 1880.
North between sections 14 & 15, 40.00 chains, set
post for $\frac{1}{4}$ section corner from which:

A Pine 18 in dia bears N80°E 73 LKS dist

A Pine 24 in dia bears N15°W 26 LKS dist

DIAGRAM

T14S $\frac{1}{4}$ R33E
S15 S14

Description of corner evidence found:

20" x 12' PP snag blazed scribe (S) N 80°E 48.2 ft

Description of monument and accessories I established to perpetuate the
original location of this corner:

From original BT I set a 3 $\frac{1}{4}$ " aluminum cap on 2 $\frac{1}{2}$ " x 30" aluminum pipe
3" above ground.


From which I mark new BT's:

A Fir 6" dia. bears S68°E, 5.9 ft. scribed $\frac{1}{4}$ S14 BT

A Fir 8" dia. bears S23°W, 19.0 ft. scribed $\frac{1}{4}$ S15 BT

Bearings and distance to center of tree compass variance 20°.

Brass LS 1844 disc in lower blaze.



I hereby certify the above corner monument was
re-established as herein described on November 21,
1981.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David E. Scott

OREGON
JULY 13, 1979
DAVID E. SCOTT
1844

Office of.....SURVEYOR..... County of.....GRANT.....
State of.....OREGON....., I hereby certify that the within instrument was filed in this office
for record on the.....5..... day of.....April....., 19.....87.....
.....Robert D. Bryant..... by.....
(COUNTY OFFICIAL) (DEPUTY)