


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Set by B. Robb, Contract 357, dated July 2, 1880.
North between sections 13 & 18; 40 chains set
stone 14x12x10 for $\frac{1}{4}$ section corner from which:

A Pine 24in dia bears N35°E 127 LKS dist

A Pine 30in dia bears S40°W 61 LKS dist



Description of corner evidence found:

A PINE S40°W, 40.2 ft. to blaze, face rotted
Found mound of 6 stones, all 6x8x4 plus or minus.

Description of monument and accessories I established to perpetuate the original location of this corner:

At location of mound I set a $3\frac{1}{4}$ " aluminum cap on a $2\frac{1}{2}$ "x30" aluminum
pipe 3" above ground marked

From which I marked new BT's:


A 6" Fir bears West 39.1 ft. distance scribed $\frac{1}{4}$ S13 BT

A 8" Fir bears S17°E 33.3 ft. distance scribed $\frac{1}{4}$ S18 BT

Distance and bearing to center of tree with 20° compass variance.

Brass LS 1844 disc in lower blazes.

I hereby certify the above corner monument was
re-established as herein described on November 7,
1981.



REGISTERED
PROFESSIONAL
LAND SURVEYOR

David E. Scott

OREGON
JULY 13, 1979
DAVID E. SCOTT
1844

Office of.....SURVEYOR..... County of.....GRANT.....
State of...OREGON....., I hereby certify that the within instrument was filed in this office
for record on the 5 day of April, 1982
Robert D. Bryant by
(COUNTY OFFICIAL) (DEPUTY)