

CERTIFIED RECORD OF LAND CORNER MONUMENTATION.

History of original corner establishment:

FIELD NOTES OF BAMFORD ROBB OF TOWNSHIP 14S, RANGE 33E, WM
CONTRACT NO 357, DATED JULY 2, 1880 , page 5

EAST ON true line between secs 14 & 23

32.50 Brook 10 lks wide flows N through deep rugged cañon
40.00 Set post for $\frac{1}{4}$ sec cor in mound of stone

RESET BY PROPORTIONATE MEASUREMENT

FIELD NOTES OF GEO. F. RIGBY CONTRACT 216 DATED MARCH 19, 1938 page 13

40.66 Proportionate measurement

Set an iron post, 3 ft. long, 1 in. diam., 10 ins in the
ground to bedrock, and in a mound of stone to top, for

$\frac{1}{4}$ sec cor., with brass cap mkd $\frac{1}{4}$ S 14
Description of corner evidence found: $\frac{1}{4}$ S 23--
2 $\frac{1}{8}$ inch brass cap marked 1939
on 1 inch iron rod in mound of rock.

from which


A fir 14 ins diam bears N36°00' E 37 lks
dist, mkd $\frac{1}{4}$ S 14 B T

A pine, 24 ins diam bears S 8°45' E 107 lks
dist., mkd $\frac{1}{4}$ S 23 B T

a pine 30 inches diam S 8°45' E 70.62 feet

open blaze marked $\frac{1}{4}$ S 23 BT

a fir 24 inches diam N 36° E 24.4 feet dead and down



Description of monument and accessories | established to perpetuate the
original location of this corner:

FROM EXISTING BRASS CAP MARKED A NEW BT

A JUNIPER 8 inches diam N 10° E 12.5 feet dist marked ($\frac{1}{4}$ S 14) (BT)
bearing and distance to center of tree, LS washer in lower blaze

I hereby certify the above corner monument was
re-established as herin described on June 19, 1982

See CS 726



Office of..... SURVEYOR..... County of..... GRANT.....
State of..... OREGON....., I hereby certify that the within instrument was filed in this office
for record on the..... 2..... day of..... Sept....., 19.....
Robert D. Baggett by.....
(COUNTY OFFICIAL) (DEPUTY)