

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Original corner established in 1901 by George Campbell,


Set stone 28x10x10 marked with 5 notches on S E E edges from which:

A 22" pine brs. N36°34'E 206 lks.

A 34" pine brs. S50°5'E 174 lks.

A 24" pine brs. S64°37'W 288 lks.

A 30" pine brs. N31°42'W 230 lks.



MD5 1114

Description of corner evidence found: 20x11x10 stone marked with 5 notches E and S firmly set in stone mound.

Pine stump brs. N36°E 136.9'

Pine windfall brs. S50°E 115' to root hole.

Pine stump brs. S62°W 192'

Pine stump brs. N31°W 151'

Description of monument and accessories established to perpetuate the original location of this corner:

Cap marked

Set 2 1/4 x 30" aluminum pipe with 2 1/2" aluminum cap rising 10" in stone mound. Buried original stone alongside.

New BTS:

9" PP brs. N37°E 30.9'

marked T145 R35E 58 BT

10" PP brs. S40°E 5.9'

marked T145 R35E 517 BT

9" PP brs. S65°W 30.7'



marked T145 R35E 518 BT

15" PP brs. N79°W 25.1'

marked T145 R35E 57 BT

T145 R35E

57 58
518 517
1988
LS 1020



I hereby certify the above corner was perpetuated as described in Dec. 1988.

Office of County Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 9 day of May, 1989
Robert W. [Signature] by _____
(COUNTY OFFICIAL) (DEPUTY)